ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	15	T Dasarahalli
Street ID	**Street Name**	**Significant Landmark**
W0223, W0191, W0195, W0225, W0123, W0208, W0206, W	NA, Vinayaka Lyt 1st Crs, Veera Anjaneya Temple Rd	DASARAHALLI
Segment No.	**Total Length (m)**	
15/S-W0223/S070427	76.57	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	12.04	77.513866	13.043759	77.513971	13.043724	New masid road	Cross road
2	14.12	77.514943	13.043413	77.515069	13.043384	New masid road	Cross road
3	8.78	77.514358	13.043155	77.514282	13.043183	New masid road	Cross road
4	4.03	77.513352	13.042981	77.513360	13.043017	NH4 service road	Chapalamma circle road
5	6.47	77.513474	13.042936	77.513501	13.042988	NH4 service road	Nagamunesh wara temple road
6	4.94	77.514221	13.042701	77.514240	13.042741	NH4 service road	Amogha hotel road
7	8.04	77.514540	13.042594	77.514555	13.042665	NH4 service road	Ayappa mess road
8	9.91	77.517536	13.040954	77.517570	13.041037	NH4 service road	Bharathi theaTRE ROAD
9	8.24	77.517833	13.040698	77.517855	13.040769	NH4 service road	excel kalyana mantapa road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of CC road from Excel Kalyana Mantapa road, Bharathi theatre road Lakshmaiah building road and Amogha hotel side road link to NH4 road in	1500000	2018-2019
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender		015-20-000011
Work Order No.	**Work Order Date**	**Period of Extention**

ಸ.ಕಾ.ಖಾ.ಅ. ಬಾಗಲಗುಂಟೆ

EE/DD/WO/407/19-20	20/09/2019	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/09/2019	19/09/2020	Yes

Contractor Details

Name of Contractor	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)**
MANJUNATH N C		0.00
Phone No.	**E-Mail ID**	
9611148295		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
0		archana
Date of Inspection	**Remarks**	
03/10/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI Ward No: 15 Ward Name: T Dasarahalli Street ID: W0223, W0191, W0195, W0225,